

# HOW TO CUT CROWN MOLDING

	Miter 45° Right	Miter 45° Left	Keep Right Side	Keep Left Side
RIGHT OUTSIDE CORNER	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
LEFT OUTSIDE CORNER		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
RIGHT INSIDE CORNER		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
LEFT INSIDE CORNER	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	